1	2	3	4	5
15	Tank at Budapanahalli ...	Byadgi ...	...	...
16	Tank at Vadavi ...	Shirahatti ...	...	...
17	Tank at Tarikop ...	Shirahatti ...	...	...
18	Tank at Doni ...	Mundargi ...	...	...
19	Tank at Mundavad ...	do ...	...	...
20	Bandhara near Bagewadi ...	do ...	...	...
21	Tank at Chikkawadatti ...	do ...	...	...
22	Tank at Mustikop ...	do ...	...	...
III	*Projects which are found to be not feasible on preliminary investigation.*			
23	Tank at Gudasolkop ...	Haveri ...	...	...
24	Bandhara near Hale Ritti ...	do ...	...	...
25	Proposed tank at Krishnapur ...	do ...	...	...
26	Bandhara near Hulihalli, across Asundi Nala ...	Ranebennur ...	...	...
27	Proposed tank at Aremallapur...	do ...	...	...
28	Tank at Makanur ...	do ...	...	...
29	Tank to the east of Gudadad Anavri	do ...	...	...
30	Tank near Yettinahalli near Masur	Hirekerur ...	...	...
31	Tank at Hirekebbur ...	do ...	...	...
32	Tank at Chikkabbur ...	do ...	...	...
33	Tank at Betkerur ...	do ...	...	...
34	Bandhara across Neeralgi nala near Kyasnur. ...	Hangal ...	...	...
35	Bandhara near Muthalli ...	Shiggaon ...	...	...
36	Tank at Guddadachennapur ...	do ...	...	...
37	Bandhara near Gundur ...	do ...	...	...
38	Tank near Hulgur ...	do ...	...	...
39	Tank at Harogere ...	Mundargi ...	...	...
40	Tank across Hirehalla near Mundargi.	do ...	...	...
41	Bandhara near Ramanahalli ...	do ...	...	...

REPAIRS AND RESTORATION OF TANKS IN HIREKERUR TALUK.

* *Q.*—648. Sri G. B. SHANKARRAO (Hirekerur).—

Will the Government be pleased to state :—

(*a*) the number of tanks restored and repaired in Hirekerur Taluk after reorganisation ;

(*b*) the expenditure incurred over each of them ;

(*c*) the number of them still requiring restoration and repair; (yearwise figures may be furnished in respect of (*a*) and (*b*) ?

A.—Sri H. K. VEERANNA GOWDH. (Minister for Public Works and Electricity).—

(*a*) and (*b*) *Vide* Statement appended.

(*c*) About 200 tanks.

Statement showing the number of tanks restored and repaired in Hirekerur Taluk and expenditure incurred on them after re-organisation.

Sl. No.	Name of work	1956-57 Rs.	1957-58 Rs.	1958-59 Rs.	1959-60 Rs.	1960-61 Rs.	Remarks
1	2	3	4	5	6	7	8
	Works taken up in 1956-57.						
	Repairs to tank in survey.						
1.	No. 6 at Burdikatti ...	506	...	...	...	...	...
2.	No. 491 at Chinnamulgund.	138	...	...	...	...	...
3.	No. 11 at Dasankop ...	4,911	...	...	...	...	...
4.	No. 194 at Havasbhavi ...	975	...	...	...	...	...
5.	No. 280 at Kachavi ...	3,101	...	...	...	...	...
6.	No. 3 at Kalvihalli ...	122	...	...	...	...	...
7.	No. 82 at Nulgeri ...	6,947	...	...	...	...	...
	Total...	16,700					
	Works taken up in 1957-58.						
1.	No. 78 at Dommalli		1,769	...	...	...	...
2.	No. 45 at Yettinhalli		2,865	...	...	...	...
3.	No. 96 at Balambid		3,061	...	...	...	...
4.	No. 100 at Kalvihalli		4,342	...	...	...	...
5.	No. 4 at Bhogavi		179	...	...	...	...
6.	No. 89 at Kalgond		2,045	...	...	...	...
7.	No. 58/67 Hirehalli		216	...	...	...	...
8.	No. 296 at Chinmulgund... ...		167	...	...	...	...
9.	No. 113 at Bhogavi		245	...	...	...	...
10.	No. 111 at Hirekonti		1,579	...	...	...	...
11.	No. 119 at Chikkonti		218	...	...	...	...
12.	No. 116 at Chikkonti		1,799	...	...	...	...
13.	No. 225 at Chikkerur		242	...	...	...	...
14.	No. 163 at Hirekonti		906	...	...	...	...
15.	No. 50 at Chupadhalli		335	...	...	...	...
16.	No. 10 at Kachavi		1,506	...	...	...	...
17.	No. 74 at Masangi		1,322	...	...	...	...
	Total...		22,796				

1	2	3	4	5	6	7	8
	Works taken up in 1958-59.						
1.	No. 65 at Godchikond	...	...	4,757	...	...	...
2.	No. 30 at Kalgond	...	...	600	...	...	...
3.	No. 2 at Godchikond	...	...	2,373	...	...	...
4.	No. 37 at Kalgond	...	...	750	...	...	...
5.	No. 13 at Hullatti	...	...	871	...	...	...
6.	No. 205 at Ablur	...	...	395	...	...	...
7.	No. 53 at Gundgatti	...	...	4,627	...	...	...
8.	No. 35 at Kalgond	...	...	2,575	...	...	...
9.	No. 21 at Kadalikop	...	...	1 596	...	...	...
		Total		18,544			
	Works taken up in 1959-60.						
1.	No. 94 at Divgihalli	...	...	...	5,704	...	...
2.	No. 109 at ,,	...	...	...	2,272	...	...
3.	No. 296 at Chinmulgund	...	...	...	3,693	...	...
4.	No. 237 at Satenhalli	...	...	...	461	...	...
5.	No. 157 at Divigalli	...	...	...	3,612	4,830	...
6.	No. 43 at ,,	...	...	...	3,183	1,413	...
7.	No. 51 at Betkerur	...	...	...	1,415	794	...
8.	No. 261 at Betkerur	...	...	...	1,858	4	...
9.	No. 92 at Chikkonti	...	...	...	10,560	220	...
10.	No. 12 at Satenhalli	...	...	...	861	...	...
11.	No. 196 at Divgihali	...	...	...	3,250	4,868	...
12.	No. 40 at Satenhalli	...	...	...	17,260	1,678	...
13.	No. 268 at Betkerur	...	...	...	692	165	...
14.	No. 101 at Nittur	...	...	...	2,524	...	...
15.	No. 58 at Jawalli	...	...	...	7,111	1,774	...
16.	No. 14 at Kargi	...	...	...	2,724	...	...
17.	No. 75 ,,	...	...	...	18,261	2,158	...
18.	No. 122 at Madlur	...	...	...	3,267	...	...
19.	No. 138 ,,	...	...	...	2,787	...	...
20.	No. 217 at Satenhalli	...	...	...	2,734	...	...
21.	No. 51 ,,	...	...	...	521	219	...
22.	No. 52 at Apinkop	...	...	...	2,754	...	...
23.	No. 136 at Satenhalli	...	...	...	489	...	...
24.	No. 18 at Purkondikop	...	...	...	11,876	1,494	...
25.	No. 16 at Havasbhavi	...	...	...	14,175	463	...
26.	No. 30 at Bhogavi	...	...	...	7,770	16	...
27.	No. 139/63 at Havasbhavi Yogikop.	...	...	...	10,203	786	...
28.	No. 57 at Kargi	...	...	...	909	1,823	...
29.	No. 199 at Satenhalli	...	...	...	3,317	...	...

(Sri H. K. VEERANNA GOWDH)

1	2	3	4	5	6	7	8
30	No. 223 at Madlur	...	...	...	1,601	266	...
31	No. 8, 15 and 19 at Jogihalli.	...	...	...	12,284	...	...
32	No. 179 at Godchikond	...	...	...	4,264	655	...
33	No. 13 ,,	...	...	...	3,320	1,234	...
34	No. 213 at Kod	...	...	...	16,858	1,949	...
35	No. 125 at Holbikond	...	...	...	8,388	1,512	...
36	No. 78 ,,	...	...	...	1,447	861	...
37	No. 134 at Burdikatti	...	...	...	585	217	...
38	No. 100 at Halvihalli	...	...	...	2,093	...	...
39	No. 154 at Dommnalli	...	...	...	600	...	...
40	No. 129 at Nulgeri	...	...	...	7,594	...	...
41	No. 12 at Aladkatti	...	...	...	2,303	...	...
42	No. 231 at Dudihalli	...	...	...	3,836	532	...
43	No. 9 at Holbikond	...	...	...	4,615	...	...
44	No. 3 at Kalvihalli	...	...	...	5,675	491	...
45	No. 114 at Burdikatti	...	...	...	3,769	...	...
46	No. 119 at Varah	...	...	...	3,149	154	...
47	No. 116 at Channalli	...	...	...	3,533	259	...
48	No. 187 at Yettinhalli	...	...	...	1,450	318	...
49	No. 1 at Narah	...	...	...	5,307	621	...
50	No. 27 at Holbikond	...	...	...	1,211	...	...
51	No. 132 at Arikatti	...	...	...	2,166	122	...
52	No. 202 at Dudihalli	...	...	...	5,000	380	...
53	No. 66 at Harihalli	...	...	...	2,312	202	...
54	No.29/31 at Newwi/Kodihalli	...	...	...	9,189	...	...
55	No. 100 at Hoskatti	...	...	...	20,095	...	...
56	No. 60 at Maddinkop	...	...	...	4,807	...	...
57	No. 43 at Yellapur	...	...	...	680	186	...
58	No. 80 at Aladkatti	...	...	...	2,633	...	...
				Total ...	2,87,004		
	Work taken up in year 1960-61.						
1	No. 25 at Mugalihalli	...	...	...	...	4,498	...
2	No. 99 at Dudihalli	...	...	...	...	4,019	...
3	No. 3 and 59 at Madlur	...	...	...	...	596	...
4	No. 141 at Lingapur	...	...	...	...	321	...
5	No. 1-0 at Godchikond	...	...	...	...	1,377	...
6	No. 107 at Burdikatti	...	...	...	...	...	...

1	2	3	4	5	6	7	8
7	No. 48 at Nulgeri	...	...	...	...	6,520	...
8	No. 89 at Kalgond	...	...	...	...	7,852	...
9	No. 125 at Hadrihalli	...	...	...	...	2,140	...
10	No. 3 at Dhupadhalli	...	...	...	...	1,737	...
11	No. 13 at Betkerur	...	...	...	...	3,317	...
12	No. 109 at Hadribalii	...	...	...	...	3,675	...
13	No. 206 ,,	...	...	...	...	3,317	...
14	No. 98 at Balambid	...	...	...	...	2,031	...
15	No. 29 at Betkerur	...	...	...	...	892	...
16	No. 17 at Aladkatti	...	...	...	...	1,248	...
17	No. 105 at Kalvihalli	...	...	...	...	2,448	...
18	No. 241 at Hevasbhavi	...	...	...	...	1,634	...
19	No. 38 at Mugalihalli	...	...	...	...	855	...
20	No. 26 at Balambid	...	...	...	...	483	...
21	No. 93 at Hadrihalli	...	...	...	...	795	...
22	No. 115 at Chikkonti	...	...	...	...	920	...
23	No. 50 at Hadrihalli	...	...	...	...	2,120	...
24	No. 148 at Yettinahalli	...	...	...	...	3,053	...
25	No. 11 at Kunchur	...	...	...	...	1,411	...
26	No. 90 at Kalvihalli	...	...	...	...	3,069	...
27	No. 205 at Ablus	...	...	...	...	3,354	...
28	No. 140 at Channalli	...	...	...	...	1,561	...
29	No. 78 at Holbakond	...	...	...	...	...	...
30	No. 294 at Hirekerur	...	...	...	...	...	...
31	No. 30 at Kalgond	...	...	...	...	...	...
32	No. 2 at Godchikond	...	...	...	...	...	...
33	No. 35 at Chickabudihalli	...	...	...	...	1,061	...
34	No. 124 at Divgikalli	...	...	...	...	...	...
35	No. 82 at Nulgeri	...	...	...	...	...	...
36	No. 53 at Gundgatti	...	...	...	...	...	...
37	No 63 at Dommalli	...	...	...	...	16,855	...
38	No. 124 at Godchikond	...	...	...	...	9,182	...
						1,24,955	...
				Grand Total	...	4,69,999	

LOANS SANCTIONED THROUGH SERVICE CO-OPERATIVE SOCIETY, SIDLAGHATTA KASABA.

*Q.—743. Sri J. VENKATAPPA (Sidlaghatta).—

Will the Government be pleased to state :—

the various kinds of loans together with the amount sanctioned and distributed through Service Co-operative Society, Sidlaghatta Kasaba, and the purpose for which loans were sanctioned ?